

Ambuja Cements Limited

(Unit-Rauri)

Ambient Air Quality Monitoring Report for the Month of June 2010

Sr. No.	Station	Respirable Suspended Particulate Matter			Total Suspended Particulate Matter		
		Average	Minimum	Maximum	Average	Minimum	Maximum
1	Station No. 1 (Rauri – North side of the Project)	75.37	59.50	86.75	164.83	128.55	191.24
2	Station No. 2 (Dhauti – West side of the Project)	72.76	52.58	93.37	159.24	118.40	199.51
3	Station No. 3 (Pleri – South side of the Project)	68.86	59.73	80.95	158.88	140.79	183.96